800 Independence Ave., S.W. Washington, D.C. 20591

Federal Aviation Administration

**Transmittal Letter 15-25** 

October 23, 2015

## PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53 (AVAILABLE ON THE WEB AT HTTP://NFDC.FAA.GOV)

The enclosed Standard Instrument Approach Procedures, Departure Procedures/Takeoff Minimums and Fix Actions are effective as indicated.

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:

.....EFFECTIVE UPON PUBLICATION.....

	AIRAC	STATE	CITY	AIRPORT	FDC	FDC	- SUBJECT
	DATE				NUMBER	DATE	
	10-Dec-15	WV	Moundsville	Marshall County	5/6267	10/16/15	RNAV (GPS) RWY 24, Orig

FDC **5/6267** MPG IAP MARSHALL COUNTY, MOUNDSVILLE, WV. RNAV (GPS) RWY 24, ORIG... DELETE NOTE: VISIBILITY REDUCTION BY HELICOPTERS NA. CHART NOTE: PROCEDURE NA AT NIGHT. CHART NOTE: HELICOPTER VISIBILITY REDUCTION BELOW 1 SM NOT AUTHORIZED.

THIS IS RNAV (GPS) RWY 24 ORIG-A. 1510141509-PERM