	•	7					
US DEPARTURE PROCEDURES/TAKEOFF MINIMUMS							
Bearings, headings, courses and radials are magnetic. Elevations an indicated. Ceilings are in feet above airport elevation. Distances are	d altitudes are in feet MSL. in nautical miles, except vi	Altitudes are minimum altitudes u sibilities which are in statute mile	nless otherwise s or in feet RVR.				
COORDINATED WITH ATA ALPA	χ αορά χ Νβάα	APA X OTHER (Specify) PHX TRACON	ZAB ARTCC Airport Manager				
			All por c flutiuger				
		:					
IFR DEPARTURE PROCEDURE:							
RWY 5, right turn; RWY 23, climb d in holding pattern (hold SW, RT, O of flight.	irect TFD VORTAC 48° inbound) to (; continue climb MEA for direction					
			· · · · ·				
<i>,</i>							

-						
(DEVELOPED BY H			APPROVED BY		
SIGNATURE	RESTATING AND	2 5/ 19/85 OKC FIFO	HARRY J. BOSS	, Manager, OKC FIFO	DATE 4-21-85	
CITY AND STATE Casa Gran		AIRPORT Casa Grande Mur	nicipal	effective date 9/26/85	amdt. no. 1	

.