U.S. DEPARTMENT OF TRANSPORTATION – FEDERAL AVIATION ADMINISTRATION TAKEOFF MINIMUMS AND OBSTACLE DEPARTURE PROCEDURES (ODP)

Bearings, headings, courses, tracks and radials are magnetic. Elevation and altitudes are in feet MSL. Altitudes are minimum altitudes unless otherwise indicated. Cellings are in feet above airport elevation. Distances are in naulical miles. Visibilities are in statute miles or feet RVR unitess otherwise indicated.

City, StateAirportEffective DateAmdt. No.MANILA, ARMANILA MUNI19 SEPTEMBER 20131

TAKEOFF MINIMUMS:

RWY 18, 36, STANDARD.

TEXTUAL DEPARTURE PROCEDURES:

TAKEOFF OBSTACLE NOTES:

NOTE: RWY 18, POLE 140 FT FROM DER, 440 FT RIGHT OF CENTERLINE, 26 FT AGL/266 FT MSL. POLE 529 FT FROM DER, 449 FT RIGHT OF CENTERLINE, 39 FT AGL/279 FT MSL. TANK 211 FT FROM DER, 190 FT LEFT OF CENTERLINE, 13 FT AGL/253 FT MSL. TREES BEGINNING 1807 FT FROM DER, LEFT AND RIGHT OF CENTERLINE, UP TO 95 FT AGL/334 FT MSL.

NOTE: RWY 36, POLE 584 FT FROM DER, 554 FT LEFT OF CENTERLINE, 33 FT AGL/270 FT MSL. POLE 585 FT FROM DER, 530 RIGHT OF CENTERLINE, 28 FT AGL/268 FT MSL. VEHICLE ON ROAD 569 FT FROM DER, 4 FT LEFT OF CENTERLINE, 24 FT AGL/265 FT MSL. TREES BEGINNING 811 FT FROM DER, LEFT AND RIGHT OF CENTERLINE, UP TO 116 FT AGL/351 FT MSL.

CONTROLLING OBSTACLES:

U.S. DEPARTMENT OF TRANSPORTATION - FEDERAL AVIATION ADMINISTRATION TAKEOFF MINIMUMS AND OBSTACLE DEPARTURE PROCEDURES (ODP)

Bearings, headings, courses, tracks and radials are magnetic. Elevation and attitudes are in feet MSL. Attitudes are minimum attitudes unless otherwise indicated. Ceilings are in feet above airport elevation. Distances are in nautical miles. Visibilities are in statute miles or feet RVR unless otherwise indicated.

City, State Airport **Effective Date** Amdt. No. MANILA, AR MANILA MUNI **19 SEPTEMBER 2013** 1

REMARKS:

FLIGHT INSPECTED BY

James Hawley

REQUIRED EFFECTIVE DATE:

ROUTINE

DEVELOPED BY:

Mum 5/16/13
Mum AJV-353 JILL M. OLSON (COLTON CROWDER

11/19/2012

APPROVED BY:

COORDINATED WITH

AOPA, NBAA, ZFW, AMGR

CHANGES:

TAKEOFF OBSTACLE NOTES REVISED.

REASONS:

ANALPV SURVEY DATED 9/02/2011