U.S. DEPARTMENT OF TRANSPORTATION – FEDERAL AVIATION ADMINISTRATION TAKEOFF MINIMUMS AND OBSTACLE DEPARTURE PROCEDURES (ODP)

Bearings, headings, courses, tracks and radials are magnetic. Elevation and altitudes are in feet MSL. Altitudes are minimum altitudes unless otherwise indicated. Ceilings are in feet above airport elevation. Distances are in nautical miles. Visibilities are in statute miles or feet RVR unless otherwise indicated.

City, State	Airport	Effective Date	Amdt. No.
GREER, SC	GREENVILLE SPARTANBURG INTL	15 OCTOBER 2015	1A

TAKEOFF MINIMUMS:

RWY 4, 22, STANDARD.

TEXTUAL DEPARTURE PROCEDURES:

RWY 4: CLIMB HEADING 038.21 TO 2500 BEFORE TURNING LEFT.

VISUAL CLIMB OVER AIRPORT:

TAKEOFF OBSTACLE NOTES:

NOTE: RWY 4, TREES 1422 FT FROM DER, 832 FT RIGHT OF CENTERLINE, UP TO 65 FT AGL/1001 FT MSL.

CONTROLLING OBSTACLES:

OBSTACLES MANDATING ODP ROUTE DEVELOPMENT:

RWY 4 - 3671 FT MSL TOWER 351012.00N/0821726.00W.

ONALITY OHECKED

FAA FORM 8260-15A (12/12) Page 1 of 2

U.S. DEPARTMENT OF TRANSPORTATION – FEDERAL AVIATION ADMINISTRATION TAKEOFF MINIMUMS AND OBSTACLE DEPARTURE PROCEDURES (ODP)

Bearings, headings, courses, tracks and radials are magnetic. Elevation and altitudes are in feet MSL. Altitudes are minimum altitudes unless otherwise indicated. Ceilings are in feet above airport elevation. Distances are in nautical miles. Visibilities are in statute miles or feet RVR unless otherwise indicated.

City, State	Airport	Effective Date	Amdt. No.
GREER, SC	GREENVILLE SPARTANBURG INTL	15 OCTOBER 2015	1A

REMARKS:

FLIGHT INSPECTED BY: REQUIRED EFFECTIVE DATE:

ROY F TURNER

Digitally signed by FICO 07/01/2015

JULIE A MORGAN

ROUTINE

DEVELOPED BY: Jul 27, 2015

Digitally signed by

PETER GUIMOND PETER R GUIMOND AJV-5413 05/21/2015

May 21, 2015

APPROVED BY:

Digitally signed by

ADOLFO URRUTIA JULIE A MORGAN AJV-5410

COORDINATED WITH: Jul 27, 2015

ATA, ALPA, APA, AOPA, NBAA, ZTL, GSP APP CON, GSP ATCT, AMGR.

CHANGES:

1. AMENDED RWY 4 TAKEOFF OBSTACLE NOTES.

2. DELETED 3468 FT MSL TOWER FROM RWY 4 CONTROLLING OBSTACLES.

REASONS:

1. NEW OBSTACLE STUDY.

2. FORMATTED IN ACCORDANCE WITH CURRENT DOCUMENTATION POLICY.

ONALITY 3 CHECKED

FAA FORM 8260-15A (12/12) Page 2 of 2