## FEDERAL AVIATION ADMINISTRATION FLIGHT STANDARDS SERVICE TAKEOFF MINIMUMS AND OBSTACLE DEPARTURE PROCEDURES (ODP) TITLE 14 CFR PART 97.37

Bearings, headings, courses, tracks and radials are magnetic. Elevations and altitudes are in feet, MSL. Altitudes are minimum altitudes unless otherwise indicated Ceilings are in feet above airport elevation. Distances are in nautical miles. Visibilities are in statute miles or feet RVR unless otherwise indicated.

<u>CITY, STATE</u> MOUNTAIN VILLAGE, AK					AIRPORT MOUNTAIN VILLAGE				EFFECTIVE DATE 30 JANUARY 2020	AMDT NO 2
	F MINIMUMS 0: Standaf									
TEXTUAL	DEPARTU	RE PROCEDU	IRES:							
VISUAL (	CLIMB OVER	AIRPORT:								
	F OBSTACL WY 2: LIGHT		OM DER, 4	7 FT RIGHT	OF CENTERLI	INE, 341 FT MSL	. LIGHTING 9 FT	FROM DER, 4	47 FT LEFT OF CENTI	ERLINE, 340
<b>NOTE: R</b> \\ 299 FT M		TING 9 FT FR	OM DER,	47 FT LEFT	OF CENTERLI	NE, 299 FT MSL	. LIGHTING 10 F	T FROM DER,	47 FT RIGHT OF CEN	ITERLINE,
CONTRO	LLING OBS	TACLES:								
REMARK	<u>.s</u> :									
FLIGHT II	NSPECTED EARBY	BY:	Y: Digitally signed by  ALLAN WILL  Aug 06, 2019					OFFICE SYM		<b>ATE</b> : 6/11/19
DEVELOPED BY: Digitally si  MARK CIARLONE MARK CIARLONE  Nov 29,			ed by LONE					OFFICE SYM AJV-5423		PATE: 27/2018
APPROVED BY: JULIE MORGAN		,	Digitally <b>ALLA</b>	signed by <b>N WILL</b> 6, 2019				OFFICE SYM AJV-5420		ATE:
REQUIRE ROUTINE	ED EFFECTI	/E DATE:								
COORDIN A4A	NATED WITH ALPA	<u>l</u> : <u>AOPA</u>	<u>APA</u>	<u>HAI</u>	<u>NBAA</u>					
	$\boxtimes$	$\boxtimes$			$\boxtimes$					
OTHER: ZAN, AMO	GR									
CHANGE	S - REASON	IS:								

1. CHANGED TAKEOFF OBSTACLE NOTES - NEW SURVEY.

2. ADDED ALPA TO COORDINATED WITH BLOCK - ALL DP'S ARE COORDINATED WITH ALPA PER 8260.19H, PARA 8-6-13A.