

PREPARED BY THE PRODUCT SUPPORT GROUP, AJV 34

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
8-Jan-15	PR	Aguadilla	Rafael Hernandez	4/8726	11/21/14	RNAV (GPS) RWY 26, Orig-A

AIRAC Date: 8 JANUARY 2015

FDC **4/8726** BQN IAP RAFAEL HERNANDEZ, AGUADILLA, PR. RNAV (GPS) RWY 26, ORIG-A... CHART PROFILE NOTE: VGSI AND DESCENT ANGLES NOT COINCIDENT. CHART NOTE: HELICOPTER VISIBILITY REDUCTION BELOW 3/4 SM NA. 34:1 IS NOT CLEAR. VDP AT 1.10 MILES TO RW26. CHANGE ALTIMETER SETTING NOTE TO READ: WHEN LOCAL ALTIMETER SETTING NOT RECEIVED, PROCEDURE NA. THIS IS RNAV (GPS) RWY 26 ORIG-B. 1411042203-PERM