

**Federal Aviation  
Administration**

**Transmittal Letter 08-12**

**MAY 02, 2008**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows: .....EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DAT	SUBJECT
04/30/08	MO	SPRINGFIELD	SPRINGFIELD-BRANSON NATIONAL	8/5455		VOR OR TACAN RWY 20, AMDT 18B

**AIRAC Date: 30 APRIL 2008**

FDC 8/5455 SGF FiiP SPRINGFIELD-BRANSON NATIONAL, SPRINGFIELD, MO. ~ VOR OR TACAN RWY 20, AMDT 18B ... CIRCLING CAT AIB MDA 1760/HAA 492, ~ CATCMDA 1820/HAA 552. ALTERNATE MINIMUMS: STANDARD, EXCEPT CAT E 800-2 1/4 THIS IS VOR OR TACAN RWY 20, AMDT 18C.