800 Independence Ave., S.W. Washington, D.C. 20591

Federal Aviation Administration

Transmittal Letter 15-17

July 2, 2015

PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53 (AVAILABLE ON THE WEB AT HTTP://NFDC.FAA.GOV)

The enclosed Standard Instrument Approach Procedures, Departure Procedures/Takeoff Minimums and Fix Actions are effective as indicated.

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:

_______EFFECTIVE UPON PUBLICATION

AIRAC

STATE

CITY

AIRPORT

FDC

FDC

SUBJECT

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
20-Aug-15	MD	Crisfield	Crisfield Muni	5/4450	06/29/15	Takeoff Minimums and (Obstacle) DP, Orig

EFFECTIVE 20 AUGUST 2015

FDC **5/4450** W41 ODP CRISFIELD MUNI, CRISFIELD, MD. TAKEOFF MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES ORIG... CHANGE AIRPORT NAME TO: CRISFIELD-SOMERSET COUNTY AIRPORT. THIS IS TAKEOFF MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES, ORIGA. 1506251217-PERM