

U.S. Department  
of Transportation

800 Independence Ave., S.W.  
Washington, D.C. 20591

**Federal Aviation  
Administration**

**Transmittal Letter 15-14**

**May 22, 2015**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows: .....EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
25-Jun-15	CA	Marysville	Yuba County	5/6348	05/06/15	RNAV (GPS) RWY 32, Orig-B

**EFFECTIVE 25-JUN-2015**

**FDC 5/6348 MYV IAP YUBA COUNTY, MARYSVILLE, CA. RNAV (GPS) RWY 32, ORIG-B... DELETE NOTE: CIRCLING TO RWY 23 NA AT NIGHT CHART NOTE: NIGHT LANDING: RWY 5, 23 NA. THIS IS RNAV (GPS) RWY 32 ORIG-C. 1505041806-PERM**