

**Federal Aviation
Administration**

Transmittal Letter 14-13

May 9, 2014

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
26-Jun-14	MI	Ann Arbor	Ann Arbor Muni	4/3744	4/29/14	VOR RWY 6, AMDT 13C

AIRAC Date: 26 JUNE 2014

FDC 4/3744 ARB IAP ANN ARBOR MUNI, ANN ARBOR, MI. VOR RWY 6, AMDT 13C...
CHANGE THRE 831 TO TDZE 831. THIS IS VOR RWY 6, AMDT 13D.
1404032129-PERM