

**Federal Aviation
Administration**

Transmittal Letter 16-09

March 11, 2016

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC,
LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS,
MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs,
Identified as follows:EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
28-Apr-16	OR	The Dalles	Columbia Gorge Rgnl/The Dalles Muni	5/0502	02/29/16	COPTER LDA/DME RWY 25, Amdt 1

AIRAC Date: 28 APRIL 2016

FDC 5/0502 DLS IAP COLUMBIA GORGE RGNL/THE DALLES MUNI, THE DALLES, OR. COPTER LDA/DME
RWY 25, AMDT 1... CHANGE THRE 243 TO TDZE 243. THIS IS COPTER LDA/DME RWY 25, AMDT 1A.
1512221333-PERM