

PREPARED BY THE PRODUCT SUPPORT GROUP, AJV 34

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
8-Jan-15	PR	Aguadilla	Rafael Hernandez	4/8718	11/21/14	VOR/DME OR TACAN RWY 26, Orig-A

AIRAC Date: 8 JANUARY 2015

FDC **4/8718** BQN IAP RAFAEL HERNANDEZ, AGUADILLA, PR. VOR/DME OR TACAN RWY 26, ORIG-A... CHART PROFILE NOTE: VGSI AND DESCENT ANGLES NOT COINCIDENT. DELETE VDP. CHANGE DISTANCE IN PROFILE: BQN VORTAC TO RW26 FROM 0.20 TO 0.30. THIS IS VOR/DME OR TACAN RWY 26 ORIG-B. 1411042203-PERM