

**Federal Aviation
Administration**

Transmittal Letter 17-21

August 25, 2017

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
12-Oct-17	PR	Aguadilla	Rafael Hernandez	7/6264	8/22/17	VOR/DME OR TACAN RWY 26, Orig-C

AIRAC Date: 12 OCTOBER 2017

FDC 7/6264 BQN IAP RAFAEL HERNANDEZ, Aguadilla, PR. VOR/DME OR TACAN
RWY 26, ORIG-C ... DELETE THRE 194, CHART TDZE 210. S-26 MDA 620/HAT 410
ALL CATS, VIS CATS C/D 1 1/8. CHART NOTE: RWY 26 HELICOPTER VISIBILITY
BELOW 3/4 SM NOT AUTHORIZED. CHART NOTE: DME REQUIRED. CHART
PLANVIEW NOTE: DME REQUIRED. DELETE NOTE: HELICOPTER VISIBILITY
REDUCTION BELOW 3/4 SM NA. CHART FAS OBST: 320 TOWER
183002N/0670605W. THIS IS VOR OR TACAN RWY 26, ORIG-D 1708081634-PERM