Federal Aviation Administration

Transmittal Letter 18-06

**January 26, 2018** 

## PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53 (AVAILABLE ON THE WEB AT HTTP://NFDC.FAA.GOV)

The enclosed Standard Instrument Approach Procedures, Departure Procedures/Takeoff Minimums and Fix Actions are effective as indicated.

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:

| AIRAC<br>DATE | STATE | CITY    | AIRPORT      | FDC<br>NUMBE | FDC<br>DATE | SUBJECT                                      |
|---------------|-------|---------|--------------|--------------|-------------|--|
| 1-Mar-18      | MA    | Beverly | Beverly Rgnl | 8/2210       | 1 1/16/18   | Takeoff Minimums and<br>Obstacle DP, Amdt 3A |

AIRAC Date: 1 MARCH 2018

FDC **8/2210** BVY ODP BEVERLY RGNL, Beverly, MA. TAKEOFF MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES AMDT 3A... CHANGE AIRPORT NAME FROM BEVERLY MUNI TO BEVERLY RGNL. ALL OTHER DATA REMAINS THE SAME. THIS IS TAKEOFF MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES, AMDT 3B. 1801081330-PERM