

**Federal Aviation
Administration**

Transmittal Letter 17-18

July 14, 2017

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
17-Aug-17	TX	Bay City	Bay City Muni	7/7163	7/6/17	VOR-A, Amdt 4C

AIRAC Date: 17 AUGUST 2017

FDC 7/7163 BYY IAP BAY CITY MUNI, Bay City, TX. VOR-A, AMDT 4C... CHART
MAP: OXUSY/PSX 26.32 DME FIX. DELETE MAP: OXUSY/PSX 23.32 DME FIX.
THIS IS VOR-A, AMDT 4D. 1706221227-PERM