

**Federal Aviation
Administration**

Transmittal Letter 16-17

July 1, 2016

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DAT	SUBJECT
18-Aug-16	MO	Mountain Grove	Mountain Grove Memorial	6/9744	6/15/16	RNAV (GPS) RWY 8, Orig

AIRAC Date: 18 AUGUST 2016

FDC 6/9744 1MO IAP MOUNTAIN GROVE MEMORIAL, MOUNTAIN GROVE, MO.
RNAV (GPS) RWY 8, ORIG... DELETE THRE 1452. CHART TDZE 1476. LNAV HAT
664 ALL CATS. THIS IS RNAV (GPS) RWY 8, ORIG-A. 1604141923-PERM