

**Federal Aviation
Administration**

Transmittal Letter 18-03

December 15, 2017

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
1-Feb-18	MN	Rushford	Rushford Muni	7/2747	12/4/17	Takeoff Minimums and Obstacle DP, Amdt 2

AIRAC Date: 1 FEBRUARY 2018

FDC **7/2747** 55Y ODP RUSHFORD MUNI, Rushford, MN. TAKEOFF MINIMUMS AND
(OBSTACLE) DEPARTURE PROCEDURES AMDT 2... CHANGE AIRPORT NAME
FROM RUSHFORD MUNI TO RUSHFORD MUNI-ROBERT W BUNKE FIELD. ALL
OTHER DATA REMAINS THE SAME. THIS IS TAKEOFF MINIMUMS AND (OBSTACLE)
DEPARTURE PROCEDURES, AMDT 2A. 1710121241-PERM