

**Federal Aviation
Administration**

Transmittal Letter 18-11

April 6, 2018

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMB	FDC DATE	SUBJECT
24-May-18	VT	West Dover	Deerfield Valley Rgnl	8/2942	3/22/18	RNAV (GPS) RWY 1, Orig-A

AIRAC Date: 24 MAY 2018

FDC **8/2942** 4V8 IAP DEERFIELD VALLEY RGNL, West Dover, VT. RNAV (GPS) RWY 1, ORIG-A... DELETE: DESCENT ANGLE 3.05/TCH 40. CHART PROFILE NOTE: VISUAL SEGMENT - OBSTACLES. DELETE NOTE: DME/DME RNP-0.3 NA. PBN REQUIREMENTS NOTE: RNP APCH. THIS IS RNAV (GPS) RWY 1, ORIG-B. 1803152016-PERM