

**Federal Aviation  
Administration**

**Transmittal Letter 05-26**

**November 18, 2005**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,  
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,  
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:  
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBE	FDC DATE	SUBJECT
22-Dec-05	IL	Springfield	Abraham Lincoln Captial	5/0638	11/15/05	ILS OR LOC RWY 4, AMDT 25

**AIRAC Date: 22 December 2005**

FDC 5/0638 SPI FI/P ABRAHAM LINCOLN CAPITAL, SPRINGFIELD, IL. ILS OR LOC RWY 4  
AMDT 25...DELETE NOTE: PROCEDURE NA WHEN CONTROL TOWER CLOSED.  
ALTERNATE MINS STANDARD EXCEPT: NA WHEN CONTROL TOWER CLOSED. NA WHEN  
LOCAL WEATHER NOT AVAILABLE. ILS, CATEGORY D, 700-2. THIS IS ILS OR LOC RWY 4  
AMDT 25A.