

**Federal Aviation
Administration**

Transmittal Letter 18-09

March 9, 2018

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMB	FDC DATE	SUBJECT
26-Apr-18	ND	Oakes	Oakes Muni	8/3892	3/1/18	Takeoff Minimums and Obstacle DP, Amdt 1

AIRAC Date: 26 APRIL 2018

FDC **8/3892** 2D5 ODP OAKES MUNI, Oakes, ND. TAKEOFF MINIMUMS AND
(OBSTACLE) DEPARTURE PROCEDURES AMDT 1... TAKEOFF MINIMUMS RWY 17,
35: NA - ENVIRONMENTAL. THIS IS TAKEOFF MINIMUMS AND (OBSTACLE)
DEPARTURE PROCEDURES, AMDT 1A. 1802261807-PERM