

U.S. Department
of Transportation

800 Independence Ave., S.W.
Washington, D.C. 20591

**Federal Aviation
Administration**

Transmittal Letter 16-07

February 12, 2016

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME,
LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
31-Mar- 16	AZ	Prescott	Ernest A Love Field	6/4364	02/08/16	RNAV (GPS) Y RWY 3R, Orig

EFFECTIVE 31 MARCH 2016

FDC **6/4364** PRC IAP ERNEST A LOVE FIELD, PRESCOTT, AZ. RNAV (GPS) Y
RWY 3R, ORIG... CHANGE THRE 5022 TO TDZE 5022. DELETE NOTE: RWY
3R STRAIGHT-IN AND CIRCLING AND CIRCLING RWY 30 NA AT NIGHT..
CHART NOTE: NIGHT LANDING: RWY 3R, 12, 30 NA. THIS IS RNAV (GPS) Y
RWY 3R, ORIG-A. 1601171036-PERM