

**Federal Aviation
Administration**

Transmittal Letter 19-06

January 25, 2018

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
28-Feb-19	IL	Dixon	Dixon Muni-Charles R Walgreen Field	8/6724	1/11/19	VOR-A, Amdt 10B

AIRAC Date: 28 FEBRUARY 2019

FDC **8/6724** C73 IAP DIXON MUNI-CHARLES R WALGREEN FIELD, Dixon, IL. VOR-
A, AMDT 10B... DELETE NOTE: NIGHT LANDING RWY 8, 26 NA. DELETE NOTE:
HELICOPTER VISIBILITY REDUCTION BELOW 1 SM NA. THIS IS VOR-A, AMDT 10C.
1810051706-PERM