

**Federal Aviation  
Administration**

**Transmittal Letter 18-04**

**December 29, 2017**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,  
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,  
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:  
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
1-Feb-18	MI	Ann Arbor	Ann Arbor Muni	7/8393	12/5/17	RNAV (GPS) RWY 6, Amdt 2B

**AIRAC Date: 1 FEBRUARY 2018**

FDC **7/8393** ARB IAP ANN ARBOR MUNI, Ann Arbor, MI. RNAV (GPS) RWY 6, AMDT  
2B... CHART NOTE: CIRCLING NA TO RWYS 12 AND 30. THIS IS RNAV (GPS) RWY 6,  
AMDT 2C. 1709071726-PERM