## Federal Aviation Administration

### **Transmittal Letter 19-16**

June 14, 2019

## PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53 (AVAILABLE ON THE WEB AT HTTP://NFDC.FAA.GOV)

### The enclosed Standard Instrument Approach Procedures, Departure Procedures/Takeoff Minimums and Fix Actions are effective as indicated.

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows: 						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
7/18/2019	IL	Litchfield	Litchfield Muni	9/5134	5/30/2019	RNAV (GPS) RWY 18, Orig-B

# AIRAC Date: 18 July 2019

FDC 9/5134 3LF IAP LITCHFIELD MUNI, Litchfield, IL. RNAV (GPS) RWY 18, ORIG-B... DELETE CIRCLING MINIMUMS. THIS IS RNAV (GPS) RWY 18, ORIG-C. 1905291257-PERM