Federal Aviation Administration

**Transmittal Letter 19-16** 

June 14, 2019

## PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53 (AVAILABLE ON THE WEB AT HTTP://NFDC.FAA.GOV)

The enclosed Standard Instrument Approach Procedures, Departure Procedures/Takeoff Minimums and Fix Actions are effective as indicated.

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:

**AIRAC** FDC FDC **STATE CITY SUBJECT AIRPORT** DATE **NUMBER** DATE RNAV (GPS) RWY 27, 7/18/2019 ILLitchfield Litchfield Muni 9/5132 5/30/2019 Orig-A

## AIRAC Date: 18 July 2019

FDC 9/5132 3LF IAP LITCHFIELD MUNI, Litchfield, IL. RNAV (GPS) RWY 27, ORIG-A... DELETE CIRCLING MINIMUMS. DELETE PLANVIEW NOTE: PROCEDURE NA FOR ARRIVALS AT VLA VORTAC VIA V12 WESTBOUND. CHART PLANVIEW NOTE: PROCEDURE NA FOR ARRIVALS AT VLA VORTAC ON V12 WESTBOUND. THIS IS RNAV (GPS) RWY 27, ORIG-B. 1905291254-PERM