Federal Aviation Administration

Transmittal Letter 19-16

June 14, 2019

PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53 (AVAILABLE ON THE WEB AT HTTP://NFDC.FAA.GOV)

The enclosed Standard Instrument Approach Procedures, Departure Procedures/Takeoff Minimums and Fix Actions are effective as indicated.

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
7/18/2019	CA	Jackson	Westover Field Amador County	9/5154	6/3/2019	GPS RWY 1, Orig-B

AIRAC Date: 18 July 2019

FDC 9/5154 JAQ IAP WESTOVER FIELD AMADOR COUNTY, Jackson, CA. GPS RWY 1, ORIG-B... DELETE CIRCLING MINIMUMS. CHART NOTE: WHEN LOCAL ALTIMETER SETTING NOT RECEIVED, USE SACRAMENTO EXECUTIVE ALTIMETER SETTING. DELETE NOTE: IF LOCAL ALTIMETER SETTING NOT RECEIVED, USE SACRAMENTO EXECUTIVE ALTIMETER SETTING. MISSED APPROACH: CLIMB TO 4500 ON 006 COURSE TO VOHBO AND HOLD. THIS IS GPS RWY 1, ORIG-C. 1905291311-PERM