## PREPARED BY THE PRODUCT SUPPORT GROUP, AJV-34

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:

......EFFECTIVE UPON PUBLICATION

| AIRAC<br>DATE | STATE | CITY        | AIRPORT         | FDC<br>NUMBER | FDC DATE | SUBJECT                       |
|---------------|-------|-------------|-----------------|---------------|----------|-------------------------------|
| 5/30/13       | FL    | Brooksville | Hernando County | 3/6959        | 4/1/13   | RNAV (GPS) RWY<br>21, Amdt 1A |

FDC 3/6959 BKV FI/P IAP HERNANDO COUNTY, BROOKSVILLE, FL. RNAV (GPS) RWY 21, AMDT 1A... CHART NOTE: RWY 21 STRAIGHT-IN/CIRCLING AND CIRCLING RWY 3/27 NA AT NIGHT. CHANGE HELICOPTER VISIBILITY REDUCTION NOTE TO READ: HELICOPTER VISIBILITY REDUCTION BELOW 1 SM NOT AUTHORIZED. CHART PROFILE NOTE: VGSI AND DESCENT ANGLES NOT COINCIDENT. THIS IS RNAV (GPS) RWY 21, AMDT 1B.