Federal Aviation Administration

Transmittal Letter 19-18

July 12, 2019

PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53 (AVAILABLE ON THE WEB AT HTTP://NFDC.FAA.GOV)

The enclosed Standard Instrument Approach Procedures, Departure Procedures/Takeoff Minimums and Fix Actions are effective as indicated.

By amending: \$97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; \$97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; \$97.27 NDB, NDB/DME; \$97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; \$97.31 RADAR SIAPs; \$97.33 RNAV SIAPs; and \$97.35 COPTER SIAPs, Identified as follows:

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
8/15/2019	NJ	Blairstown	Blairstown	9/0963	6/28/2019	RNAV (GPS) RWY 25, Amdt 2B

AIRAC Date: 15 AUGUST 2019

FDC 9/0963 1N7 IAP BLAIRSTOWN, Blairstown, NJ. RNAV (GPS) RWY 25, AMDT 2B... DELETE CIRCLING MINIMUMS. PBN REQUIREMENTS NOTE: RNP APCH. DELETE NOTE: DME/DME RNP-0.3 NA. CHART NOTE: RWY 25 HELICOPTER VISIBILITY REDUCTION BELOW 1 SM NOT AUTHORIZED. DELETE NOTE: HELICOPTER VISIBILITY REDUCTION BELOW 1 SM NA. THIS IS RNAV (GPS) RWY 25, AMDT 2C. 1906241534-PERM