

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

The enclosed Standard Instrument Approach Procedures, Departure Procedures/Takeoff Minimums and Fix Actions are effective as indicated.

| By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION | | | | | | |
|--|-------|--------|-----------------|------------|----------|--------------------------|
| AIRAC DATE | STATE | CITY | AIRPORT | FDC NUMBER | FDC DATE | SUBJECT |
| 17-Sep-15 | NY | Hudson | Columbia County | 5/5217 | 08/04/15 | RNAV (GPS) RWY 3, Orig-A |

FDC 5/5217 1B1 IAP COLUMBIA COUNTY, HUDSON, NY. RNAV (GPS) RWY 3, ORIG-A... DELETE NOTE: NIGHT LANDING: RWY 21 NA.

THIS IS RNAV (GPS) RWY 3 ORIG-B. 1508031812-PERM