800 Independence Ave., S.W Washington, D.C. 20591

Federal Aviation Administration

Transmittal Letter 15-08

February 27, 2015

PREPARED BY THE PRODUCT SUPPORT GROUP, AJV-34 (AVAILABLE ON THE WEB AT HTTP://NFDC.FAA.GOV)

The enclosed Standard Instrument Approach Procedures, Departure Procedures/Takeoff Minimums and Fix Actions are effective as indicated.

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:

......EFFECTIVE UPON PUBLICATION

| AIRAC DATE | STATE | CITY | AIRPORT | FDC NUMBER | FDC DATE | SUBJECT |
|---------------|-------|-----------|----------------|---------------|-------------|---------------------------|
| 2-Apr-15 | WI | East Troy | East Troy Muni | 5/8342 | 02/11/15 | RNAV (GPS) RWY 8, Orig |

FDC **5/8342** 57C IAP EAST TROY MUNI, EAST TROY, WI. RNAV (GPS) RWY 8, ORIG... LP HAT 389 ALL CATS. LNAV HAT 389 ALL CATS. DELETE THRE 843. CHART TDZE 851. DELETE NOTE: VISIBILITY REDUCTION BY HELICOPTERS NA. CHART NOTE: HELICOPTER VISIBILITY REDUCTION BELOW 1 SM NA. DELETE NOTE: CIRCLING RWY 26 NA AT NIGHT. CHART NOTE: NIGHT LANDING: RWY 26 NA.

THIS IS **RNAV (GPS) RWY 8 ORIG-A**. 1502020037-PERM