

**Federal Aviation
Administration**

Transmittal Letter 19-26

November 1, 2019

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
12/5/2019	OH	West Union	Alexander Salamon	9/9048	10/23/2019	RNAV (GPS) RWY 5, Orig-B

AIRAC Date: 5 DECEMBER 2019

FDC 9/9048 AMT IAP ALEXANDER SALAMON, West Union, OH. RNAV (GPS) RWY 5, ORIG-B... DELETE CIRCLING MINIMUMS. THIS IS RNAV (GPS) RWY 5, ORIG-C. 1910211533-PERM