

U.S. Department  
of Transportation

800 Independence Ave., S.W.  
Washington, D.C. 20591

**Federal Aviation  
Administration**

**Transmittal Letter 17-12**

**April 21, 2017**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

| AIRAC<br>DATE | STATE | CITY    | AIRPORT                   | FDC<br>NUMBER | FDC<br>DATE | SUBJECT                        |
|---------------|-------|---------|---------------------------|---------------|-------------|--------------------------------|
| 25-May-17     | MA    | Bedford | Laurence G<br>Hanscom Fld | 7/7798        | 4/5/17      | RNAV (GPS) Z RWY<br>29, Amdt 1 |

**AIRAC Date: 25 MAY 2017**

**FDC 7/7798** BED IAP LAURENCE G HANSCOM FLD, BEDFORD, MA. RNAV (GPS) Z RWY 29, AMDT 1... CHART TDZE 128, DELETE THRE 123. LPV DA 328. LNAV/VNAV DA 614. LNAV HAT 512 ALL CATS. THIS IS RNAV (GPS) Z RWY 29, AMDT 1A. 1702241556-PERM