

**Federal Aviation  
Administration**

**Transmittal Letter 20-01**

**November 15, 2019**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,  
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,  
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:  
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
1/2/2020	CO	Rifle	Rifle Garfield County	9/0308	11/12/2019	LOC/DME-A, Amdt 9A

**AIRAC Date: 2 JANUARY 2020**

FDC 9/0308 RIL IAP RIFLE GARFIELD COUNTY, RIFLE, CO. LOC/DME-A, AMDT 9A... CHART CIRCLING ICON. DELETE NOTE: CIRCLING NOT AUTHORIZED AT NIGHT SOUTH OF RWY 8-26. CHART NOTE: CIRCLING NA S OF RWY 8-26 AT NIGHT. THIS IS LOC/DME-A, AMDT 9B. 1911071654-PERM