U.S. Department of Transportation

Federal Aviation Administration

Transmittal Letter 20-13

May 1, 2020

PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53 (AVAILABLE ON THE WEB AT HTTP://NFDC.FAA.GOV)

The enclosed Standard Instrument Approach Procedures, Departure Procedures/Takeoff Minimums and Fix Actions are effective as indicated.

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:

.......EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
6/18/2020	ОН	Columbus	Ohio State University	0/5534	4/21/2020	ILS OR LOC RWY 9R, Amdt 5A

AIRAC Date: 18 JUNE 2020

FDC 0/5534 OSU IAP OHIO STATE UNIVERSITY, COLUMBUS, OH. ILS OR LOC RWY 9R, AMDT 5A... CHART NOTE: CIRCLING RWY 23 NA AT NIGHT. EQUIPMENT REQUIREMENTS NOTE: ADF REQUIRED FOR PROCEDURE ENTRY. EQUIPMENT REQUIREMENTS NOTE: ADF REQUIRED. DELETE PLANVIEW NOTE: ADF REQUIRED. DELETE NOTE: ADF REQUIRED. THIS IS ILS OR LOC RWY 9R, AMDT 5B. 2004201709-PERM