

**Federal Aviation
Administration**

Transmittal Letter 23-01

November 11, 2022

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
12/29/2022	LA	Rayville	John H Hooks Jr Meml	2/3525	10/20/2022	RNAV (GPS) RWY 18, Amdt 1B

AIRAC Date: 29 DECEMBER 2022

FDC 2/3525 M79 IAP JOHN H HOOKS JR MEML, RAYVILLE, LA. RNAV (GPS) RWY 18, AMDT 1B... CHART
PROFILE NOTE: *640 WHEN USING BASTROP ALTIMETER SETTING. PBN REQUIREMENTS NOTE: RNP
APCH - GPS. DELETE PBN REQUIREMENTS NOTE: RNP APCH. DELETE PROFILE NOTE: *LNAV ONLY.
THIS IS RNAV (GPS) RWY 18, AMDT 1C. 2208191910-PERM