

**Federal Aviation
Administration**

Transmittal Letter 21-01

November 13, 2020

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
12/31/2020	IN	Anderson	Anderson Muni-Darlington Field	0/9468	10/21/2020	RNAV (GPS) RWY 30, Orig-B

AIRAC Date: 31 DECEMBER 2020

**FDC 0/9468 AID CHART ANDERSON MUNI-DARLINGTON FIELD, ANDERSON, IN.
RNAV (GPS) RWY 30, ORIG-B... DELETE NOTE: CIRCLING RWY 12, 36 NA AT
NIGHT. CHART VDP AT 1.04 NM TO RW30*. THIS IS RNAV (GPS) RWY 30, ORIG-C.
2009231519-PERM**