

U.S. Department
of Transportation

800 Independence Ave., S.W
Washington, D.C. 20591

**Federal Aviation
Administration**

Transmittal Letter 15-08

February 27, 2015

**PREPARED BY THE PRODUCT SUPPORT GROUP, AJV-34
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
2-Apr-15	TX	Sweetwater	Avenger Field	5/9519	02/12/15	RNAV (GPS) RWY 22, Orig

FDC 5/9519 SWW IAP AVENGER FIELD, SWEETWATER, TX. RNAV (GPS) RWY 22, ORIG... LPV DA 2605. LNAV/VNAV DA 2605. LNAV HAT 325 ALL CATS. CHART TDZE 2355. DELETE THRE 2337.

THIS IS RNAV (GPS) RWY 22 ORIG-A. 1502050016-PERM