

**Federal Aviation
Administration**

Transmittal Letter 15-06

January 30, 2015

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
5-Mar-15	IL	Benton	Benton Muni	5/3926	01/20/15	RNAV (GPS) RWY 18, Orig

AIRAC Date: 5 MARCH 2015

FDC 5/3926 H96 IAP BENTON MUNI, BENTON, IL. RNAV (GPS) RWY 18, ORIG...
LNAV HAT 416 ALL CATS. CHART TDZE 444. DELETE THRE 440. THIS IS RNAV
(GPS) RWY 18 ORIG-A. 1501150043-PERM