Federal Aviation Administration

Transmittal Letter 19-16

June 14, 2019

PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53 (AVAILABLE ON THE WEB AT HTTP://NFDC.FAA.GOV)

The enclosed Standard Instrument Approach Procedures, Departure Procedures/Takeoff Minimums and Fix Actions are effective as indicated.

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:

AIR. DA		STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
7/18/	2019	IN	Angola	Tri-State Steuben County	9/5213	5/30/2019	RNAV (GPS) RWY 5, Orig-D

AIRAC Date: 18 July 2019

FDC 9/5213 ANQ IAP TRI-STATE STEUBEN COUNTY, Angola, IN. RNAV (GPS) RWY 5, ORIG-D... DELETE CIRCLING MINIMUMS. DELETE NOTE: CIRCLING RWY 23 NA AT NIGHT. THIS IS RNAV (GPS) RWY 5, ORIG-E. 1905291413-PERM