

**Federal Aviation  
Administration**

**Transmittal Letter 20-01**

**November 15, 2019**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,  
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,  
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:  
.....EFFECTIVE UPON PUBLICATION

| AIRAC<br>DATE | STATE | CITY                | AIRPORT             | FDC<br>NUMBER | FDC<br>DATE | SUBJECT             |
|---------------|-------|---------------------|---------------------|---------------|-------------|---------------------|
| 1/2/2020      | CA    | Twentynine<br>Palms | Twentynine<br>Palms | 9/8358        | 10/28/2019  | VOR RWY 26, Amdt 2A |

**AIRAC Date: 2 JANUARY 2020**

FDC 9/8358 TNP IAP TWENTYNINE PALMS, Twentynine Palms, CA. VOR RWY 26,  
AMDT 2A... CHART CIRCLING ICON. THIS IS VOR RWY 26, AMDT 2B. 1910182030-  
PERM