

**Federal Aviation  
Administration**

**Transmittal Letter 13-20**

**August 16, 2013**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs,  
Identified as follows:...EFFECTIVE UPON PUBLICATION

| AIRAC DATE | STATE | CITY      | AIRPORT        | FDC<br>NUMBER | FDC DATE | SUBJECT               |
|------------|-------|-----------|----------------|---------------|----------|-----------------------|
| 9/19/13    | MS    | Indianola | Indianola Muni | 3/9452        | 8/7/13   | VOR/DME B, AMDT<br>5B |

**AIRAC Date: 19 SEPTEMBER 2013**

FDC **3/9452** IDL FI/P IAP INDIANOLA MUNI, INDIANOLA, MS. VOR/DME B, AMDT 5B... DELETE NOTE: PROCEDURE NA FOR ARRIVALS AT SQS VORTAC ON AIRWAY RADIAL 273. CHART NOTE: HELICOPTER VISIBILITY REDUCTION BELOW 1 SM NOT AUTHORIZED. CHART PLANVIEW NOTE: PROCEDURE NA FOR ARRIVALS AT GLH VOR/DME ON AIRWAY RADIALS 010 CW 143. THIS IS VOR/DME B, AMDT 5C.