

**Federal Aviation
Administration**

Transmittal Letter 21-19

July 23, 2021

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
9/9/2021	OH	Columbus	Rickenbacker Intl	1/9902	5/20/2021	ILS OR LOC RWY 5R, Amdt 3D

AIRAC Date: 9 SEPTEMBER 2021

FDC 1/9902 LCK IAP RICKENBACKER INTL, COLUMBUS, OH. ILS OR LOC RWY 5R, AMDT 3D ... CIRCLING
CAT A/B MDA 1240/HAA 496, CAT C MDA 1280/HAA 536, CAT D MDA 1400/HAA 656. THIS IS ILS OR LOC
RWY 5R, AMDT 3E, ILS OR LOC RWY 5R (SA CAT I), AMDT 3E, ILS OR LOC RWY 5R (CAT II), AMDT 3E
2105041347-PERM