

U.S. Department
of Transportation

800 Independence Ave., S.W
Washington, D.C. 20591

**Federal Aviation
Administration**

Transmittal Letter 15-08

February 27, 2015

**PREPARED BY THE PRODUCT SUPPORT GROUP, AJV-34
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME,
LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
2-Apr-15	MT	Helena	Helena Rgnl	5/2923	02/19/15	ILS OR LOC Z RWY 27, Amdt 2

FDC 5/2923 HLN IAP HELENA RGNL, HELENA, MT. ILS OR LOC Z RWY 27,
AMD 2... CHANGE TERMINAL ROUTE FROM ZIMUM/HLN 20.00 DME CW TO
DOOKR/HLN 20.00 DME TO READ ZIMUM/HLN 20.00 DME CW (IAF) TO
DOOKR/HLN 20.00 DME (NOPT). CHANGE TERMINAL ROUTE FROM
KEDEC/HLN 20.00 DME CCW TO DOOKR/HLN 20.00 DME TO READ
KEDEC/HLN 20.00 DME CCW (IAF) TO DOOKR/HLN 20.00 DME (NOPT)..

THIS IS ILS OR LOC Z RWY 27, AMDT 2A. 1502122007-PERM