

**Federal Aviation
Administration**

Transmittal Letter 24-24

September 27, 2024

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
10/31/2024	OK	Frederick	Frederick Rgnl	4/0640	9/6/2024	RNAV (GPS) RWY 35, Orig-B

AIRAC Date: 31 OCTOBER 2024

FDC 4/0640 FDR IAP FREDERICK RGNL, FREDERICK, OK. RNAV (GPS) RWY 35, ORIG-B... CHANGE NIGHT LANDING NOTE TO READ: CIRCLING RWY 3, 12, 17, 21, 30, NA AT NIGHT. CHANGE PLAINVIEW NOTE TO READ: PROCEDURE NA FOR ARRIVALS AT SPS VORTAC ON V404 EASTBOUND. DELETE PROFILE NOTE: *LNAV ONLY. DELETE ASTERISK IN PROFILE AT WEXAV AND VDP. DELETE PROFILE NOTE: VGSI AND RNAV GLIDEPATH NOT COINCIDENT (VGSI ANGLE 3.09/TCH 46). THIS IS RNAV (GPS) RWY 35, ORIG-C. 2409051120-PERM