FEDERAL AVIATION ADMINISTRATION FLIGHT STANDARDS SERVICE TAKEOFF MINIMUMS AND OBSTACLE DEPARTURE PROCEDURES (ODP) TITLE 14 CFR PART 97.37

Bearings, headings, courses, tracks and radials are magnetic. Elevations and altitudes are in feet, MSL. Altitudes are minimum altitudes unless otherwise indicated.

	Ceilings are in t	feet above airport	elevation. Distance	es are in nautical miles. Visibilities ar	e in statute miles or feet R	RVR unless otherwise	indicated.
AIRPORT ID AQP			<u>CITY</u> APPLETO) N	<u>STATE</u>	AMDT NO ORIG-B	ACTUAL EFFECTIVE DATE 19 MAY 2022
AQP			APPLETO	אוכ	MN	ORIG-B	1) WA 1 2022
TAKEOFF MINIMUMS RWY 4, 22: NA - ENVI							
RWY 13, 31: STANDA	RD.						
TEXTUAL DEPARTUR RWY 13, CLIMB ON H			BEFORE TUR	NING RIGHT.			
RWY 31, CLIMB ON H	EADING 300.	43 TO 2000	BEFORE TURI	NING LEFT.			
VISUAL CLIMB OVER	AIRPORT:						
,	ES BEGINNIN 76 FT FROM [,	FT LEFT OF CENTERLINE, ENTERLINE, UP TO 100 FT			
OBSTACLES MANDAT REMARKS: NO RWY SURVEYS A		OUTE DEVEL	OPMENT: RW	VY 13/31: 2318 FT MSL TO	WER 451003.31N/0	0960003.27W.	
FLIGHT INSPECTED	BY				<u>OFFICE</u>	DATE	Digitally signed by
PROCESSED IAW TECHNICAL SUPPORT GROUP (AJF-17) MEMO DATED 07/07/2021, SUBJECT: GUIDANCE FOR PROCEDURAL CHANGES REQUIRING FLIGHT INSPECTION/VALIDATION.						DA	AVID TEFFETELLER Mar 01, 2022
DEVELOPED BY				Digitally signed by	<u>OFFICE</u>	DATE	
JON DENTON (KATHI	ERINE EUBAN	NKS)		DAVID TEFFETELLER Mar 01, 2022	AJV-A432		
APPROVED BY				Digitally signed by	<u>OFFICE</u>	DATE	TITLE
LONNIE EVERHART				DAVID TEFFETELLER	AJV-A430		MANAGER
REQUIRED EFFECTIVE ROUTINE	/E DATE:			Mar 01, 2022			
COORDINATED WITH	:						
A4A ALPA	AOPA 🔀	APA 🗌	HAI N	BAA OTHER: ZMP	PNM FSS, AMGR		
CHANGES - REASON 1. INCORPORATED C 2. CHANGED TAKEON	HANGES FR				A - ENVIRONMEN	TAL INCORPO	DRATED FDC NOTAM 1/7976.
3/1/2022: THIS IS A STATE CHANGES I			THE FORM AF	PPROVED ON 2/10/2022			

OUALITY 50 CHECKED