

**Federal Aviation
Administration**

Transmittal Letter 16-15

June 3, 2016

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DAT	SUBJECT
21-Jul-16	WY	Riverton	Riverton Rgnl	6/2277	5/23/16	ILS OR LOC RWY 28, Amdt 3

AIRAC Date: 21 JULY 2016

FDC 6/2277 RIW IAP RIVERTON RGNL, RIVERTON, WY. ILS OR LOC RWY 28, AMDT 3... APT ELEV 5528. CIRCLING CAT A/B/C HAA 472, CAT D HAA 592. THIS IS ILS OR LOC RWY 28, AMDT 3A. 1603311140-PERM