

**Federal Aviation
Administration**

Transmittal Letter 22-22

September 2, 2022

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
10/6/2022	OH	Upper Sandusky	Wyandot County	2/3462	8/23/2022	VOR-A, Amdt 3D

AIRAC Date: 6 OCTOBER 2022

FDC 2/3462 56D IAP WYANDOT COUNTY, UPPER SANDUSKY, OH. VOR-A, AMDT 3D... CIRCLING CAT C/D MDA 1540/HAA 710. YEVUN FIX MINIMUMS (DME REQUIRED): CIRCLING CAT B MDA 1440/HAA 610, CAT C/D MDA 1540/HAA 710, VIS CAT B 1, CAT C 2, CAT D 2 1/4. CHANGE ALTIMETER NOTE TO READ: WHEN LOCAL ALTIMETER SETTING NOT RECEIVED, USE MARION ALTIMETER SETTING: INCREASE ALL MDAS 40 FEET AND VISIBILITY CAT C/D 1/4 SM. THIS IS VOR-A, AMDT 3E. 2208191705-PERM