FEDERAL AVIATION ADMINISTRATION FLIGHT STANDARDS SERVICE ILS STANDARD INSTRUMENT APPROACH PROCEDURE TITLE 14 CFR PART 97.29

Bearings, headings, courses, tracks and radials are magnetic. Elevations and altitudes are in feet, MSL, except HAT, HAA, TCH, and RA. Altitudes are minimum altitudes unless otherwise indicated. Ceilings are in feet above airport elevation. Distances are in nautical miles unless otherwise indicated, except visibilities which are in statute miles or feet RVR.

KDNV		PROCEDURE NAME ILS OR LOC RWY 21	OF	RIGINAL/AMEN 8	<u>IDMENT</u>		<u>CIT</u> DANVI		STATE IL	
AIRPORT ELEVATION 697	<u>TDZ</u> 697		SUPERSEDE ILS OR LOC RW			<u>origina</u> i	L/AMENDMENT 7B	DATED 12/02/2021	MAG VAR 0E	EPOCH YEAF 1980
FACILITY I-DNV	COORDINATES OF		EFFECTIVE DATE OVEMBER 2023		<u>REQUI</u>	RED EFF ROUT	ECTIVE DATE INE	<u>CANCEL/SU</u>	<u>ISPEND</u>	
TERMINAL ROUTES										
FROM	FIX TYPE	<u>T0</u>	FIX TYPE	LEG TYPE	FO/FB	<u>RNP</u>	COUR	<u>SE</u>	DISTANCE	ALTITUDE
BVT VORTAC	IAF	COSMA INT	NOPT				241.4	7	19.38	2600
COSMA INT	IF	JULIP LOM					209.2	0	8.02	2600
MISSED APPROACH INST	RUCTIONS:	O 2600 DIRECT JULIP LOM A	AND HOLD, CONTINU	E CLIMB-IN-HO	OLD TO 2	2600.				
LOC: 5.59 NM AFTER JULII MISSED APPROACH INSTI CLIMB TO 1400 THEN CLIN ALTERNATE MISSED APPI	RUCTIONS: //BING RIGHT TURN TO		AND HOLD, CONTINU	E CLIMB-IN-H	OLD TO 2	2600.				
MISSED APPROACH INSTI CLIMB TO 1400 THEN CLIN	RUCTIONS: //BING RIGHT TURN TO		AND HOLD, CONTINU	E CLIMB-IN-H	OLD TO 2	2600.				
MISSED APPROACH INSTI CLIMB TO 1400 THEN CLIM ALTERNATE MISSED APPI	RUCTIONS: //BING RIGHT TURN TO ROACH INSTRUCTION		AND HOLD, CONTINU		OLD TO 2		LOM (IAF)			
MISSED APPROACH INSTI CLIMB TO 1400 THEN CLIM ALTERNATE MISSED APPI PROFILE: 1. PT R SIDE OF CO	RUCTIONS: //BING RIGHT TURN TO ROACH INSTRUCTION DURSE 029.20	I <u>S:</u>	FT WITHIN		ES OF	JULIP	LOM (IAF) IST FAF TO THLD: 5	5.59		
MISSED APPROACH INSTI CLIMB TO 1400 THEN CLIM ALTERNATE MISSED APPI PROFILE: 1. PT R SIDE OF CO 2.	RUCTIONS: MBING RIGHT TURN TO ROACH INSTRUCTION DURSE 029.20 F/	IS: OUTBOUND 2600	FT WITHIN	10 MIL	ES OF	JULIP		5.59		
MISSED APPROACH INSTI CLIMB TO 1400 THEN CLIM ALTERNATE MISSED APPI PROFILE: 1. PT R SIDE OF CO 2. 3. FAC: 209.20	RUCTIONS: MBING RIGHT TURN TO ROACH INSTRUCTION OURSE 029.20	IS: OUTBOUND 2600 AF: JULIP LOM	FT WITHIN	10 MIL	ES OF	JULIP		5.59		NAL12,
MISSED APPROACH INSTI CLIMB TO 1400 THEN CLIM ALTERNATE MISSED APPI PROFILE: 1. PT R SIDE OF CO 2. 3. FAC: 209.20 4. MIN ALT: JULIP LOM 26	RUCTIONS: MBING RIGHT TURN TO ROACH INSTRUCTION OURSE 029.20 F/ 00	IS: OUTBOUND 2600 AF: JULIP LOM	FT WITHIN DIST FAF	10 MIL TO MAP: 5.59 GS ANT: 89 OM: 252	ES OF	JULIP		5.59	IM:	پ ^{۱۵۲} /۶ _۲ 10

EQUIPMENT REQUIREMENTS NOTE:

ADF REQUIRED.

AIRPORT ID	PROCEDURE NAME	ORIGINAL/AMENDMENT	<u>CITY</u>	<u>STATE</u>	
KDNV	ILS OR LOC RWY 21	8	DANVILLE	IL	

NOTES:

CHART NOTE: CIRCLING NA TO RWYS 12 AND 30. CHART PLANVIEW NOTE: PROCEDURE NA FOR ARRIVAL ON BVT VORTAC AIRWAY RADIALS 186 CW 271.

ADDITIONAL FLIGHT DATA:

HOLD NE, LT, 209.20 INBOUND. CHART FAS OBST: 814 TREE (17-039613) 401324N/0873459W. 900 AAO 401651N/0873216W.

MINIMUMS:

TAKEOFF: SEE FAA FORM 8260-15A FOR THIS AIRPORT

ALTERNATE: NA X

CATEGORY:	A		В		С		D		E						
FINAL TYPE	DA/MDA	VIS	HAT/HAA	DA/MDA	VIS	HAT/HAA	DA/MDA	VIS	HAT/HAA	DA/MDA	VIS	HAT/HAA	DA/MDA	VIS	HAT/HAA
S-ILS 21	897	1/2	200	897	1/2	200	897	1/2	200	897	1/2	200			
S-LOC 21	1080	1/2	383	1080	1/2	383	1080	5/8	383	1080	5/8	383			
CIRCLING	1160	1	463	1160	1	463	1240	1 1/2	543	1340	2	643			

CHANGES - REASONS

1. REMOVED FEEDER FROM DANSVILLE (DNV) VORTAC TO JULIP LOM. - DNV VORTAC DECOMMISSIONING.

2. REMOVED INITIAL FROM BATAM TO COSMA INT. - FPT REQUEST.

3. DECREASED S-LOC 21 CAT C AND D VISIBILITY FROM 1/2, 3/4 TO 5/8, 5/8 SM. - UPDATED IAW 8260.3E TABLE 3-3-1.

4. MISSED APPROACH INSTRUCTIONS UPDATED FROM "CLIMB TO 1400 THEN CLIMBING RIGHT TURN TO 2600 VIA DNV VORTAC R-243 TO BUBLE INT AND HOLD" TO "CLIMB TO 1400 THEN CLIMBING RIGHT TURN TO 2600 DIRECT JULIP LOM AND HOLD, CONTINUE CLIMB-IN-HOLD TO 2600." - PER FPT REQUEST.

5. REMOVED ALTERNATE MISSED APPROACH. - PER ATC/FPT REQUEST; DNV VORTAC DECOMMISSIONING.

6. LINE 6: UPDATED GS ALT AT OM FROM 2552 TO 2523. - UPDATED EVALUATION WITH 45.7 DESIGN TCH.

7. LINE 7. UPDATED TCH FROM 45.9 TO 45.7. - DESIGN TCH.

8. ADDED EQUIPMENT REQUIREMENTS NOTES: ADF REQUIRED. - PER 8260.19I, PARA 8-6-8 (A).

9. REMOVED CHART NOTE: ALTERNATE ALTIMETER NOTE. - MOVED TO 8260-9 PART C - REMÁRKS FOR CONTINGENCY USE.

10. REMOVED ADDITIONAL FLIGHT DATA: DO NOT CHART ALTERNATE MISSED APPROACH HOLDING AT JULIP LOM. - ALTERNATE MISSED APPROACH REMOVED.

11. REMOVED ADDITIONAL FLIGHT DATA: CHART TDZE 697. - NO LONGER REQUIRED.

12. UPDATED ADDITIONAL FLIGHT DATA: FROM "HOLD NE, RT, 243.06 INBOUND" TO "HOLD NE, LT, 209.20 INBOUND." - PRIMARY MISSED APPROACH UPDATED.

13. UPDATED ADDITIONAL FLIGHT DATA: CHART FAS OBST: 803 ELEV 401617N/0873236W TO 814 TREE (17-039613) 401324N/0873459W. - NEW LOC CONTROLLING OBSTACLE.

14. ADDED ADDITIONAL FLIGHT DATA: 900 AAO 401651N/0873216W. - 7:1 APPLIED AT JULIP OM.

15. UPDATED ALTERNATE MINIMUMS FROM "ILS: STANDARD - NA WHEN LOCAL WEATHER NOT AVAILABLE.; LOC: STANDARD - NA WHEN LOCAL WEATHER NOT AVAILABLE" TO NA. - ILS IS CAT 3, UNMONITORED.

10

AIRPORT ID KDNV	PROCEDURE NAME ILS OR LOC RWY 21	1	ORIGINAL/AMENDMENT 8	<u>CITY</u> DANVILLE	<u>STATE</u> IL
COORDINATED WITH: A4A 🗌 ALPA 🔀 AOPA 🗙	APA 🗌 HAI 🗌 NBAA	X OTHER: ZU	JA, CMI APP CON, AMGR, IL AERO		
ELIGHT CHECKED BY GLEN B FREEMAN	Digitally signed by CASIMIR L TABAKA Oct 03, 2023		OFFICE FPO	DATE 09/28/2023	
DEVELOPED BY CASIMIR L. TABAKA (BARBARA GORM/		Digitally signed by CASIMIR L TABAKA	OFFICE AJV-A432	DATE 03/06/2023	
APPROVED BY CASIMIR TABAKA	Digitally signed by CASIMIR L TABAKA Oct 03, 2023	Oct 03, 2023	OFFICE AJV-A430	DATE	<u>TITLE</u> MANAGER

