Federal Aviation Administration

**Transmittal Letter 15-22** 

**September 11, 2015** 

## PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53 (AVAILABLE ON THE WEB AT HTTP://NFDC.FAA.GOV)

The enclosed Standard Instrument Approach Procedures, Departure Procedures/Takeoff Minimums and Fix Actions are effective as indicated.

By amending: \$97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; \$97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; \$97.27 NDB, NDB/DME; \$97.29 ILS, ILS/DME, MLS/DME, MLS/DME, MLS/RNAV; \$97.31 RADAR SIAPs; \$97.33 RNAV SIAPs; and \$97.35 COPTER SIAPs, Identified as follows: ......EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
15-Oct-15	GA	Baxley	Baxley Muni	5/3150	9/2/2015	RNAV (GPS) RWY 8, Amdt 1A

## AIRAC Date: 15 October 2015

FDC **5/3150** BHC IAP BAXLEY MUNI, BAXLEY, GA. RNAV (GPS) RWY 8, AMDT 1A... DELETE NOTE: WHEN VGSI INOP, STRAIGHT-IN/CIRCLING RWY 8 PROCEDURE NA AT NIGHT. DELETE NOTE: WHEN VGSI INOP, CIRCLING TO RWY 26 NA AT NIGHT. DELETE NOTE: VISIBILITY REDUCTION BY HELICOPTERS NA. CHART NOTE: HELICOPTER VISIBILITY REDUCTION BELOW 3/4 SM NOT AUTHORIZED.

THIS IS RNAV (GPS) RWY 8, AMDT 1B. 1509011955-PERM