

**Federal Aviation
Administration**

Transmittal Letter 16-11

April 8, 2016

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DAT	SUBJECT
26-May-16	AK	Anvik	Anvik	5/9206	03/23/16	RNAV (GPS) RWY 17, Orig

AIRAC Date: 26 MAY 2016

FDC 5/9206 ANV IAP ANVIK, ANVIK, AK. RNAV (GPS) RWY 17, ORIG... DELETE
NOTE: WHEN VGSI INOPERATIVE, PROCEDURE NA AT NIGHT. DELETE NOTE:
VISIBILITY REDUCTION BY HELICOPTERS NA. CIRCLING CATS A/B/C MDA
840/HAA 543, CAT D MDA 860/HAA 563. THIS IS RNAV (GPS) RWY 17, ORIG A.
1512172003-PERM